






## **Perforating Process**

- Wireline supervisor initiations the detonator by sending an electric signal from the wireline unit on surface
- The signal goes down the wireline and sets off the detonator
- The detonator ignites the detonator cord
- The detonator cord burns past the shaped charge causing them to explode






Shaped Charge side view internal components



Shaped Charge inside a gun barrel



Explosion of a shaped charge and the perforation tunnel it creates



